

## FITNESS CERTIFICATE FOR SCHOOL BUILDING

- |   |   |
|---|---|
| 1. Name of the school   | : Marjum Memorial Public School, Aalo                                       |
| 2. Location with name of Education District                                       | : Yeggo/Hydel, Aalo, District: West Siang                                   |
| 3. Classification of building   | : RCC Building ( Permanent Type).   |
| 4. Period for which the certificate is issued                                     | : 2023-24.  |
| 5. Nature of defect   | : New building. No defect detected.   |
| 6. a) Foundation and basement   | : RCC   |
| b) Super Structure  | : RCC framed structure with brick wall.                                     |
| c) Doors and Windows  | : Rectangular steel Bar.  |
| d) Wood work wrought and put up   | : Properly finished.  |
| e) Roof   | : RCC Slab.   |
| f) Flooring   | : Cement Concrete & Tiles flooring.   |
| 7. Any major defects modified which will render the building unsafe in any manner | : Visually no structural defect was detected.                               |
| 8. Whether maintenance works have been done properly                              | : New building, maintenance not required.                                   |
| Whether structure is sound or not for conducting Class.                           | : As per visual examination, the building is found to be structurally safe. |
| 9. Name of inspection Officer   | : Mr. Tumken Lollen   |

Certified that the school building of Marjum Memorial Public School, Aalo was inspected by me on 22/03/2023 and the building is found to be fit for conducting classes for the session 2023-24.

  
**Assistant Engineer**  
**Sub - Division - II**  
**PWD, Aalo**

Place: Aalo.  
Dated: 22/03/2023.

Assistant Engineer  
Sub-Division-II, P.W.D, Aalo